


## Körnungslinie 2



$d_{10}=10$   $d_{20}=35$   $d_{30}=55$   $d_{40}=64$   $d_{50}=69$   $d_{60}=75$   $d_{70}=82$   $d_{80}=90$   $d_{90}=95$   $d_k=63,9$

$\tau_{krit}=60,2$  N/m<sup>2</sup>

$U=7,5$